


## ENSURE FULL SPLINE ENGAGEMENT.

- PRESET HUB ON SHAFT AS SHOWN.
- 2) IF YOUR PUMP SHAFT VARIES FROM THE DRAWN SHAFT LENGTH, CONTACT FACTORY FOR RECOMMENDATIONS.
- TORQUE BOTH SET SCREWS TO 25 FT.LBS. USING TORQUE WRENCH.
- SHAFT SHOULD HAVE FULL SPLINE ENGAGEMENT INTO HUB, IF NOT CONTACT FACTORY FOR RECOMMENDATIONS (231) 879-3372.

THE DRAWING IS THE PROPERTY OF HAYES MFG. INC. AND IS LOAND SUBJECT TO THE COMMING THAT IT SHALL NOT BE REPRODUCED.
COPIED, LOANED OR OTHERWISE DISPOSED OF DIRECTLY OR INDIRECTLY, IT SHALL BE USED AS A MEANS OF REFERENCE TO WORK PURNISHED BY THIS COMPANY ONLY AND IS NOT TO BE SUBMITTED TO OUTSIDE PARTIES FOR EXAMINATION WITHOUT OUR CONSENT.



	3	941905-	02	D2 SAE 5 HOUSING			1
	2	HB3-89		HEX~FLX HUB			1
	1	B-065		HEX~FLX DRIVE PLATE			1
SYMBOLS  FLATNESS — STRAIGHTNESS — ANGULARITY — PERPENDICULARITY — PARALLELISM — CONCENTRICITY — TRUE POSITION — ROUNDNESS — CIRCULAR RUN OUT — TOTAL RUN OUT	DET.	PART NUMBER			DESCRIPTION		QTY.
	TOLERA OTHERN	NOT SCALE DRAWING ANCES UNLESS VISE SPECIFIED MAXIMUM					
	FRAC	GLE ±1/2° TION ±1/32 DECIMAL	PERKINS SAE 6 1/2-SAE 5 HEX-FLX COUPLING ASS'Y W/HOUSING				
CYLINDRICITY FINISH	.00	00 ±.01 00 ±.005 00 ±.0005	MATERIAL				
- UNLESS OTHERWISE SPECIFIED -			DRAWN BY	DATE	DRAWING	NO.	
REMOVE FIRST THREAD ON ALL TAPPED HOLES			SIETING	02-26	6-08 ∩41-0	041-0-HB3-89-B2	
BREAK ALL SHARP CORNERS .010 TO .020 STAMP OR MARK DRAWING NO.			CHECKED B	Y SCALE	SHEET	OF	REV.

MOD.BY CK1 CK2