
| REV | DATE | CHANGE DESCRIPTION | MOD.BY | CK1 | СК2 |
|-----|------|--------------------|--------|-----|-----|
|     |      |                    |        |     |     |



## S.A.E. 7 1/2 STUB SHAFT

|  | SYMBOLS  | DET. PART NU   |  | JMBER DESCRIPTION                       |   | DESCRIPTION               | ON                                  | QTY. |
|--|--|--|--|---|---|---------------------------|-------------------------------------|------|
|  | FLATNESS STRAIGHTNESS ANGULARITY L SQUARENESS // PARALLELISM © CONCENTRICITY the TRUE POSITION   | DO NOT SCALE DRAWING TOLERANCES UNLESS OTHERWISE SPECIFIED 125/ MAXIMUM ANGLE ±1/2' FRACTION ±1/32 DECIMAL .00 ±.01 .000 ±.005 |  |   |   |                           |                                     |      |
|  | O ROUNDNESS  CIRCULAR RUN OUT  TOTAL RUN OUT  CYLINDRICITY  FINISH   |  |  | S.A.E. 7 1/2 STUB SHAFT                 |   |                           |                                     |      |
|  | Unless otherwise specified —     Remove first thread     On all tapped holes  BREAK ALL SHARP CORNERS .010 TO .020 STAMP OR MARK DRAWING NO. |  |  | DRAWN BY<br>SIETING<br>CHECKED B<br>RJH | Υ | DATE<br>06-22-06<br>SCALE | DRAWING NO.  26-0AA52 SHEET OF REV. | _    |
|  |  |  |  |   |   |                           |                                     |      |

THIS DRAWING IS THE PROPERTY OF HAYES MFG, INC. AND IS LOANED SUBJECT TO THE CONDITION THAT IT SHALL NOT BE REPRODUCED, COPIED, LOANED OR OTHERWISE DISPOSED OF, DIRECTLY OR INDIRECTLY, IT SHALL BE USED AS A MEANS OF REFERENCE TO WORK PURNISHED B THIS COMPANY ONLY AND IS NOT TO BE SUBMITTED TO OUTSIDE PARTIES FOR EXAMINATION WITHOUT OUR CONSENT.