


NOTE: THIS STEP IS IMPORTANT TO ENSURE FULL SHAFT ENGAGEMENT.

NOTE: REMOVE HUB FROM ASS'Y, PRESET HUB ON SHAFT AS SHOWN. TORQUE BOTH SET SCREWS TO 25 FT.LBS. USING TORQUE WRENCH. SHAFT SHOULD HAVE A MINIMUM OF 3/4" OF ENGAGEMENT IF NOT CONTACT FACTORY FOR RECOMMENDATIONS (231) 879-3372 TO GET HUB PRESET USE THIS EQUATION: PERFORM CALCULATION BELOW:

2.51 - SHAFT LENGTH - HUB PRESET

IF YOUR ANSWER IS (+) SHAFT IS INSIDE OF HUB, IF YOUR ANSWER IS (-) SHAFT STICKS OUT OF HUB. (SEE BOXES)

THE DRAWING IS THE PROPERTY OF HAYES MFG, INC. AND IS LOAND SUBJECT TO THE CONDITION THAT IT SHALL NOT BE REPRODUCED. COPIED, LOANED OR OTHERWISE DISPOSED OF, DIRECTLY OR INDIFECTLY, IT SHALL BE USED AS A MEANS OF REFERENCE TO WORK PURNISHED BY THIS COMPANY ONLY AND IS NOT TO BE SUBMITTED TO OUTSIDE PARTIES FOR EXAMINATION WITHOUT OUR CONSENT.



S.A.E. 10 FIBERGLASS REINFORCED NYLON DRIVE PLATE (8) .416 HOLES EQ. SPACED ON A 11.625 B.C.

IMPORTANT INSTALLATION

IMPROPER INSTALLATION OF HUB COULD CAUSE PREMATURE WEAR AND OR FAILURE.

CHANGE DESCRIPTION

MOD.BY

ZS

CK1 CK2

RJH HM

IF YOU HAVE QUESTIONS CONCERNING LOCATION OF METAL HUB ON PUMP SHAFT PLEASE CONTACT DISTRIBUTOR OR FACTORY FOR FURTHER

BOTH HUB SET SCREWS MUST BE PROPERLY TORQUED TO 25 FT.LBS. USING TORQUE WRENCH. PLEASE CONTACT DISTRIBUTOR OR FACTORY FOR

"C" SERIES TORQUE RANGE 65-175 HP

SHEET OF REV.

		3	123008-	-E02	PUMP MOUNT PLATE				1
		2	HC3-41 C-010		C SERIES HEX~FLX HUB				1
		1			SAE 10 HEX~FLX DRIVE PLATE				
\ \ \	SYMBOLS 7 FLATNESS - STRAIGHTNESS ANGULARITY PERPENDICULARITY PERPENDICULARITY PERPENDICULARITY PERPENDICULARITY PERPENDICULARITY PERPENDICULARITY PERPENDICULARITY PERPENDICULARITY FULL POSITION ROUNDNESS CIRCULAR RUN OUT TOTAL RUN OUT TOTAL RUN OUT TOTAL RUN OUT FINISH	DET.	PART NUMBER		DESCRIPTIO			on	QTY.
		DO NOT SCALE DRAWING TOLERANCES UNLESS OTHERWISE SPECIFIED 125 MAXIMUM ANGLE ±1/2: FRACTION ±1/32 DECIMAL .00 ±.01 .000 ±.005		MANUFACTURING INC. ® TITLE HEX~FLX "C" SERIES 2 PIECE COUPLING					
	- UNLESS OTHERWI			DRAWN BY	1-	ATE		DRAWING NO.	
ON ALL TAPPED HOLES BREAK ALL SHARP CORNERS 010 TO 020			ËS	SIETING		03-20-08		C-010-HC3-41-E	റാ
			CHECKED B	Y S	SCALE U-U10-HU3-41		U-U1U-NU3-41-E	02	

BREAK ALL SHARP CORNERS .010 TO .020 CHECKED BY STAMP OR MARK DRAWING NO.