

GM 3.0 LITRE

890000-03
SAE "B" PUMP MOUNT
4.00 PUMP PILOT
2-BOLT HORIZ.
(2) 1/2-13 TAPPED HOLES
ON A 5.75 B.C.

**BOTH HUB SET SCREWS MUST BE PROPERLY
TORQUED TO 25 FT.LBS. USING TORQUE WRENCH.**
**PLEASE CONTACT DISTRIBUTOR OR FACTORY FOR
ANY FURTHER QUESTIONS.**

