

REMOVE FIRST THREAD ON ALL TAPPED HOLES

STAMP OR MARK DRAWING NO.

BREAK ALL SHARP CORNERS .010 TO .020 CHECKED BY

SIETING

08-20-08

SCALE

044-0-HB1-11-B2

SHEET OF REV.