REV	DATE	CHANGE DESCRIPTION	MOD.BY	CK1	CK2
В	03/10/2010	CHANGED TO 1011 WOODRUFF KEY	ZS		

## NOTES:

1. WARNING!!! INJURY OR DEATH FROM A ROTATING STUB SHAFT CAN OCCUR IF A CONDITION EXISTS WHICH WOULD CAUSE THE SHAFT TO BREAK OR COME APART FROM ANY PART OF THE ASSEMBLY. DEPENDING UPON THE APPLICATION (FOR EXAMPLE, FAN, PULLEY, SHEAVE, ETC.), THE AREA AROUND THE STUB SHAFT MUST BE SUFFICIENTLY GUARDED SO THAT IN THE EVENT OF FAILURE, THE GUARD WILL CONTAIN ANY AIRBORNE PARTS.

## HUB/SHAFT ORIENTATION



SYMBOLS	DET.	PART NU	IMBER		DESCRIPTI	ON		qπ
O CONCENTRICITY TRUE POSITION	DO NOT SCALE DRAWING TOLERANCES UNLESS OTHERWISE SPECIFIED 128/ MAXIMUM ANGLE ±1/2: FRACTION ±1/32 DECIMAL .00 ±.01 .000 ±.005		MANUFACTURING INC. ®					
O ROUNDNESS  P CIRCULAR RUN OUT  P TOTAL RUN OUT			BEARING SUPPORTED STUB SHAFT ASS'Y					
CYLINDRICITY FINISH			MATERIAL					
	<ul> <li>UNLESS OTHERWISE SPECIF</li> <li>REMOVE FIRST THREAD</li> </ul>		DRAWN BY	DATE		DRAWING N	10.	
ON ALL TAPPE			SIETING		13-05	1/12_	U3-C	
BREAK ALL SHARP CORNERS .010 TO .020 STAMP OR MARK DRAWING NO.			CHECKED BY	Y SCALE		143-080 SHEET OF		REV.

