

NOTES:

1. HOUSING FOR KUBOTA ENGINES DF972 - WG972

SAE "B" PUMP MOUNT 3.25 PILOT DIA., 2 BOLT VERTICAL AND HORIZONTAL AND 4 BOLT

- (4) 1/2-13 TAPPED HOLES ON A 5.75 B.C.

(4) 1/2-13 TAPPED HOLES ON A 5.00 B.C.


IMPORTANT INSTALLATION

NOTE!!!!!

IMPROPER INSTALLATION OF HUB COULD CAUSE PREMATURE WEAR AND OR FAILURE.

IF YOU HAVE QUESTIONS CONCERNING LOCATION OF METAL HUB ON PUMP SHAFT PLEASE CONTACT DISTRIBUTOR OR FACTORY FOR FURTHER INFORMATION.

BOTH HUB SET SCREWS MUST BE PROPERLY TORQUED TO 25 FT.LBS. USING TORQUE WRENCH. PLEASE CONTACT DISTRIBUTOR OR FACTORY FOR ANY FURTHER QUESTIONS.




NOTE: REMOVE HUB FROM ASS'Y, PRESET HUB ON SHAFT AS SHOWN. TORQUE BOTH SET SCREWS TO 25 FT.LBS. USING TORQUE WRENCH. SHAFT SHOULD HAVE A MINIMUM OF 3/4" OF ENGAGEMENT IF NOT CONTACT FACTORY FOR RECOMMENDATIONS (231) 879-3372 TO GET HUB PRESET USE THIS EQUATION:

PERFORM CALCULATION BELOW: 1.55 - SHAFT LENGTH = HUB PRESET

IF YOUR ANSWER IS (+) SHAFT IS INSIDE OF HUB, IF YOUR ANSWER IS (-) SHAFT STICKS OUT OF HUB. (SEE BOXES)

THIS DRAWNO. IS THE PROPERTY OF HAYES MFO, INC. AND IS LOANDS SUBJECT TO THE COMMITTO THAT IT SHALL NOT BE REPRODUCED. COPIED, LOANED OR OTHERWISE DISPOSED OF, DIRECTLY OR INDIRECTLY. IT SHALL BE USED AS A MEANS OF REFERENCE TO WORK PURNISHED BY THIS COMPANY ONLY AND IS NOT TO BE SUBMITTED TO OUTSIDE PARTIES FOR EXAMINATION WITHOUT OUT CONSENT.

NOTE: THIS STEP IS IMPORTANT TO ENSURE FULL SHAFT ENGAGEMENT.



DO NOT SCALE						
DET.	PART NUMBER		DESCRIPTION			
1 B-SMN			HEX~FLX HUB HEX~FLX FLYWHEEL PLATE			
2	HB1-03					
3	PURCHASE		5/16 DIA x 1/2 DOWEL PIN			
5	930112		BOLT KIT			
6	930100-	10	HOUSING			

	SYMBOLS FLATNESS	DET.	PART	NUMBER		DESCRIPTI	ON		QTY	
	STRAIGHTNESS ANGULARITY PERPENDICULARITY	DO NOT SCALE DRAWING TOLERANCES UNLESS OTHERWISE SPECIFIED 125 MAXIMUM ANGLE ±1/2' FRACTION ±1/32 DECIMAL		:D _	MANUFACTURING INC. ®					
	O ROUNDNESS CIRCULAR RUN OUT			"KUB	™kubota mini hex~flx ass'y					
	✓ TOTAL RUN OUT ✓ CYLINDRICITY ✓ FINISH	.00 ±.01 .000 ±.005 .0000 ±.0005	MATERIAL							
	- UNLESS OTHERWISE SPECIFIED - REMOVE FIRST THREAD ON ALL TAPPED HOLES			DRAWN BY		DATE	DRAWING NO.			
ı				SIETING		07-01-08	044-0-HB1-	00 E	200	
	BREAK ALL SHARP CORN STAMP OR MARK	CHECKED B	Y	SCALE	U44-U-FIDI-	REV.				