



HOUSING # 891200-04
SAE "B" 2-BOLT
4" PUMP PILOT
(2) 1/2-13 TAPPED HOLES
EQ. SPACED ON A 5.75 B.C.



LEFT SIDE


THIS DRAWING IS THE PROPERTY OF HAYES MFG. INC. AND IS LOANED SUBJECT TO THE CONDITION THAT IT SHALL NOT BE REPRODUCED, COPIED, LOANED OR OTHERWISE DISPOSED OF, DIRECTLY OR INDIRECTLY. IT SHALL BE USED AS A MEANS OF REFERENCE TO WORK FURNISHED BY THIS COMPANY ONLY AND IS NOT TO BE SUBMITTED TO OUTSIDE PARTIES FOR EXAMINATION WITHOUT OUR CONSENT.



FRONT

COUPLING ASSY #128063

REV	DATE	CHANGE DESCRIPTION	MOD.BY	CK1	CK2



RIGHT SIDE

10	891202	DUST COVER	1
9	891203	BOLT KIT	1
8	891200-04	HOUSING	1
7	801912	GREASE	1
6	HP-1125-S-32	HUBBARD PLUG	1
5	HX100	5/16-24x5/8 H.H.B.	6
4	H52500	NEOPRENE INSERT	6
3	123729-01	THREADED BUSHING	6
2	123207-22	COUPLING HUB	1
1	126217	FLYWHEEL PLATE	1

SYMBOLS		DET.	PART NUMBER	DESCRIPTION	QTY.
⊥ ⊥ ⊥ ⊥ ⊕					

GM 2.4 & 1.6 LITRE

08/08/2006 03:13:13 PM