


NOTE: THIS STEP IS IMPORTANT TO ENSURE FULL SPLINE ENGAGEMENT.

- 1) PRESET HUB ON SHAFT AS SHOWN.
- 2) IF YOUR PUMP SHAFT VARIES FROM THE DRAWN SHAFT LENGTH, CONTACT FACTORY FOR RECOMMENDATIONS.
- 3) TORQUE BOTH SET SCREWS TO 25 FT.LBS. USING TORQUE WRENCH.
- SHAFT SHOULD HAVE FULL SPLINE ENGAGEMENT INTO HUB, IF NOT CONTACT FACTORY FOR RECOMMENDATIONS (231) 879-3372.

THIS DRAWING IS THE PROPERTY OF HAYES MEG. INC. AND IS LOAVED SUBJECT. THE CONDITION HAIT IT SHALL BE UND BE REPRODUCED.

SUBJECT OWNED OF OTHERWISE DISPOSED OF DIRECTLY OR NUDIFICALLY. IT SHALL BE USED AS A MEANS OF REFERENCE TO WORK FURNISHED BY THIS COMPANY ONLY AND IS NOT TO BE SUBMITTED TO OUTSIDE PARTIES FOR EXAMINATION WITHOUT OUR CONSENT.



"B" SERIES TORQUE RANGE 30-75 HP

		3	123008-	GN2 PUMP MOUNT PLATE					1	
		2	HB1-91		B SERIES HEX~FLX HUB				1	
		1	B-065		SAE 6 1/2 HEX~FLX DRIVE PLAT				LATE	1
	SYMBOLS FLATNESS STRAGHTNESS STRAGHTNESS ANGULARITY PERFENDICULARITY PARALLELISM O CONCENTRICITY TRUE POSITION O ROUNDNESS O'CIRCULAR RUN OUT O'CHUNDRICITY FINISH FUNISH CYLINDRICITY FINISH	DET.	PART NU	JMBER		DESCRIPTION	ON			QTY.
		TOLERA OTHERV 125/ ANI FRAC	NOT SCALE DRAWING ANCES UNLESS WISE SPECIFIED MAXIMUM GLE ±1/2' TION ±1/32 DECIMAL DO ±.01 D0 ±.005 D0 ±.005							PMF
	CLASS HEXB-065	MAKE: X BUY:		DRAWN BY SIETING		DATE 06-25-2013	D OCE		01.0	פואי
	DESCRIPTION B-065,5,13T16/3	CHECKED B	Y	SCALE	B-065-HB1-91 SHEET OF F					