


NOTE: THIS STEP IS IMPORTANT TO ENSURE FULL SPLINE ENGAGEMENT.

- 1) PRESET HUB ON SHAFT AS SHOWN.
- 2) IF YOUR PUMP SHAFT VARIES FROM THE DRAWN SHAFT LENGTH, CONTACT FACTORY FOR RECOMMENDATIONS.
- 3) TORQUE BOTH SET SCREWS TO 25 FT.LBS. USING TORQUE WRENCH.
- 4) SHAFT SHOULD HAVE FULL SPLINE ENGAGEMENT INTO HUB, IF NOT CONTACT FACTORY FOR RECOMMENDATIONS (231) 879-3372.

THIS DRAWING IS THE PROPERTY OF HAYES MEG, INC. AND IS LOAMED SUBJECT TO THE CONDITION THAT IT SHALL BUT NOT SE REPRODUCED, COPIED, LOANED OR OTHERWISE SIGNED OF, DIRECTLY OR INDIRECTLY, IT SHALL BE USED AS A MEASEN OF REFERENCE TO WORK PURINISHED BY THIS COMPANY ONLY AND IS NOT TO BE SUBMITTED TO OUTSIDE PARTIES FOR EXAMINATION WITHOUT OUT CONSENT.



"C" SERIES TORQUE RANGE 65-175 HP

	3	123845-	16 PUMP MOUNT P		OUNT PLATE			1
	2	HC1-92	C SERIES HEX~FLX HUI		HUB		1	
	1	C-075		SAE 7 1/2 HEX~FLX DRIVE PLAT			PLATE	1
SYMBOLS FLATNESS STRAGHTNESS ANGULARITY PERPENDICULARITY PARALLELISM CONCENTRICITY THUE POSITION OR ROUNDIESS CIRCULAR RUN OUT TOTAL RUN OUT TOTAL RUN OUT CYLINDRICITY FINISH	DET.	PART N	UMBER	DESCRIPTION				QTY.
	TOLERO OTHERI 125/ AN FRAC	DO NOT SCALE DRAWING TOLERANCES UNLESS OTHERWISE SPECIFIED 125/ MAXIMUM ANGLE ±1/2' FRACTION ±1/32 DECIMAL .00 ±.01 .000 ±.005 .0000 ±.0005						
CLASS MAKE: BUY: DESCRIPTION			DRAWN BY	DATE		NG NO.		
			SIETING CHECKED E RJH	SCALE		C-075-HC1-92-(